

Fig. 1
Prior Art





Fig. 2
Prior Art



HAFT ASSEMBLY SAFETY MECHANIS

Andrew J. Whitton, et al.

Docket No. 091395-9214 (4596-TC-AU)

Sheet 2, of 6

Fig. 3




Fig. 4





Fig. 5



202201-64952001

FIG. 6





FIG. 7



2009220 64958001 10085649 022600

HAFT ASSEMBLY SAFETY MECHANIS

Andrew J. Whitton, et al.

Docket No. 091395-9214 (4596-TC-AU)

Sheet 4 of 6

Fig. 8





Fig. 9



202201 64952001 10085649 022607

HAFT ASSEMBLY SAFETY MECHANIS

Andrew J. Whitton, et al.

Docket No. 091395-9214 (4596-TC-AU)

Sheet 5 of 6

Fig. 10





Fig 11



202201-6458001

FIG. 12





FIG. 13



2022051958001 10085649-022602